




Technical Audit of SIMTRONICS Oslo (Norway) for gas detection equipment in refineries



Technical Audit of INTRA AUTOMATION at Grevenbroich (Germany) for instrumentation equipment



Technical Audit of Advanced Valves at Noida (India) for check and butterfly casted valves



Technical Audit of Essar Pipings at Hazira (India) for SAW welded tubes



Industrial damage expertise – Site of Sonatrach at Skikda (Algeria) Damage on the Alstom boiler



Industrial damage expertise – Site of Sonatrach at Skikda (Algeria) Damage on the Clark Chapman boiler




Procurement inspection – Seamless tubes inspection at Zhejiang Detrans (China)



Procurement Inspection - Dimensional and UT test at Xingda forgings Wuxi (China)



Procurement inspection – Check of the dish heads manufacturing conditions at Wuxi (China)



Procurement inspection – Dish heads final inspection at Qiangzhou Xitang Wuxi (China)



Manufacturing inspection – Check of heat treatment conditions of dish heads at Wuxi (China)




Manufacturing inspection – Stainless Steel plates cutting at Morimatsu Shanghai (China)



Manufacturing supervision - Moisture Separator Reheaters (MSR) at Dong Fang H.M. at Nansha (China)



Manufacturing supervision - MSR at Dong Fang Heavy Manufacturing Nansha (China)



Manufacturing inspection - Superheater of the MSR at Dong Fang Heavy Manufacturing Nansha (China)



Manufacturing supervision - Boiler membrane panels openings to install burners at Thermax (India)



Manufacturing inspection - Weld preparation and PT tests on dish heads at Mersen Xianda (China)




Manufacturing supervision - Drain tanks for Flamanville (France) at Excon Radek Kralove (Czech Republic)



Manufacturing supervision - Condensate tanks for Flamanville (FR) at Excon Radek Kralove (Czech Republic)



Manufacturing supervision - Shells of heat exchangers at SMPV Morimatsu Shanghai (China)



Manufacturing supervision - Shells of heat exchangers at SMPV Morimatsu Shanghai (China)



Manufacturing supervision – For Novartis Singapore Various pharmaceutical tanks and vessels at HAOXIN Nansha (China)



Manufacturing inspection – Check of the tube welds on tube sheets of LEP exchangers at Morimatsu (China)



Manufacturing inspection – Check of the manufacturing of the TEP DZ exchangers at Morimatsu (China)



Manufacturing inspection – Check of the tube expansion of the TEP DZ exchangers at Morimatsu (China)



Manufacturing inspection – Check of the tube ID after expansion at Morimatsu (China)



Manufacturing inspection – NH3 tests on LEP exchangers at Morimatsu Shanghai (China)



Manufacturing inspection – Witness of mechanical tests on probes at Morimatsu Shanghai (China)




Manufacturing inspection – Check of the electrical cabinets at Stemi St Denis en Bourg (France)



Packing inspection - Check of the demisters packing into the crates at SMPV Morimatsu Shanghai (China)



Packing inspection - Check of the crate marking so as the wooden quality and handling of the crates



Documentation checking - check of quantities and materials at SMPV Morimatsu Shanghai (China)



Shipment inspection – Check of the handling and securing equipment on trucks before shipment (China)



Shipment inspection – Check on site delivery with customer of delivered equipment quality at Hong Yang He Nuclear power station (China)



Shipment inspection – Check containers unloading and storage at SJI St Jean d’Ardières (France)



Installation supervision – Check the installation of the furnace heat treatment at SJI St Jean d’Ardières (France)



Installation supervision – Check installation of the T6 unit at SJI St Jean d’Ardières (France)



Erection supervision - Normalization furnace with quench tank for Aluminium parts at (Saint Jean Ind. France)



Site supervision - On site Moisture Separator Reheater (MSR) installation supervision at Ling Ao (China)



Site supervision – On site MSR installation supervision at Taishan (China)